

ILLEGIB

Note: Final plot, solid line, shows track as obtained by Camera No. 1
(coverage is from horizon to horizon).

Remarks:

Camera No. 1

1. Clock recording not readable.
2. Film advance malfunction resulting in varying size frames.
3. Quality of positive -- good.

Cameras No. 2 and 4

1. Vignetting -- corners very thin.
2. Clock and counters not readable on prints (generally good on negative).
3. Quality -- good.
4. Scratches in line of flight (frame 228 forward).
5. Print for camera not printed in reverse.
6. Fiducial marks reversed.

Camera No. 3

1. Shutter malfunction -- only every 5th frame useable.
2. Frame counter malfunction.
3. Clock and counter not readable.
4. Fiducial marks reversed.
5. Quality -- good.
6. Scratches.

Camera No. 5

1. Counter malfunction -- 684, 697, 736.
2. Static marks.
3. Scratches -- 728 (start of scratch), 740 (start of scratch), and 737 (emulsion).
4. Counter and clock not readable on prints.
5. Prints, in some cases, did not reproduce detail present on negative -- 742 and 771.
6. Contrast -- in some cases poor (not always due to haze).